

Technical Bulletin

Issue 2 2020/06/29



THE PROBLEM:

New build roller coaster bolts breaking during final “loaded car” testing.

THE LOCATION:

Amusement park,
Kuala Lumpur,
Malaysia.

THE SOLUTION:

LAPP UK Trained technicians verified bolts were torqued to 50% above yield.

THE OUTCOME:

2000 bolts replaced and rechecked, client delighted, riders safe.



lappuk.co.uk

