

Technical Bulletin

Issue 1 2020/06/26



THE PROBLEM:

Caterpillar D9 Track Bolt torqueing, with limited reaction point options.

THE LOCATION:


Indonesian mining site.

THE SOLUTION:

LAPP Equipment UK
Ltd MK Battery
Powered Torque Gun
with a bespoke
reaction member.

THE OUTCOME:

Job successfully
completed; client
delighted!



lappuk.co.uk

